

# Basic Detail Report



**Title Fuller Brush building following collapse of tower, 1080 Windsor Avenue, Hartford**

Date 1923

Primary Maker Unknown

Medium Photography; gelatin silver print on paper

# Basic Detail Report

Description Three-story brick industrial building. Front and sides of central

tower have collapsed, exposing interior walls. A large pile of rubble is at the foot

of the tower. A crowd of onlookers, chiefly men, has gathered. Automobiles and

a steam engine are in the street. Utility poles and wires extend in front of the

building.

Dimensions Primary Dimensions (overall height x width): 10 1/4 x 8 1/4in. (26 x

21cm)