

Basic Detail Report

Title Fuller Brush building following collapse of tower, 1080 Windsor

Avenue, Hartford

Date 1923

Primary Maker Unknown

Medium Photography; gelatin silver print on paper

Description Three-story brick industrial building. Front and sides of central tower have collapsed, exposing interior walls. A large pile of rubble is at the foot of the tower. A crowd of onlookers, chiefly men, has gathered. Automobiles and a steam engine are in the street. Utility poles and wires extend in front of the building.

Dimensions Primary Dimensions (overall height x width): 10 1/4 x 8 1/4in. (26 x 21cm)