


# Basic Detail Report



## Title Suzio Rock Crusher, Westfield Road, Meriden

Date 1957

Primary Maker Unknown

Medium Photography; gelatin silver print on Kodak Velox paper

Description A rock crusher is in a pit or quarry. A conveyor belt and heavy rock crushing machinery are at the right. A dilapidated wooden structure, possibly a headframe, is in the center. Utility poles and wires connect to a small structure built of concrete blocks, possibly housing a generator, at the right. A pile of sand or gravel is at the far left.

Dimensions Primary Dimensions (image height x width):  $2 \frac{3}{4} \times 3 \frac{15}{16}$  in. (7 x 10cm) Sheet (height x width):  $3 \frac{1}{4} \times 4 \frac{9}{16}$  in. (8.3 x 11.6cm)