


Basic Detail Report



Title Train Wreck, Tariffville, Connecticut: Coach in Water

Date 1878

Primary Maker Daniel S. Camp

Medium Photography; albumen prints on paper on cardboard mount

Description A shattered railroad coach hangs from an embankment into a river.

Debris, including portions of another coach, is in the river. Part of a wooden railroad bridge extends overhead. Men wearing dark overcoats stand on the bank of the river looking at the wreck.

Dimensions Primary Dimensions (image height x width): 3 1/16 x 3 1/8in. (7.8 x 7.9cm) Sheet (height x width): 3 1/16 x 3 1/8in. (7.8 x 7.9cm) Mount (height x width): 3 3/8 x 6 7/8in. (8.6 x 17.5cm)