


Basic Detail Report



Title Hartford Civic Center Roof Collapse

Date 1978

Primary Maker Richard Welling

Medium Photocopy; black toner on paper

Description Photocopy of a drawing of the roof of the Hartford Civic Center after its collapse, from an elevated perspective overlooking the building. Two cranes are depicted on the arena floor. The Masonic Hall appears in the background on the right.

Dimensions Sheet (height x width): 12 x 18in. (30.5 x 45.7cm)