

Basic Detail Report

Title New Haven Railroad freight train derailment, Hartford, 1959

Date 1959 March 1

Primary Maker Frank Lorenzo

Medium Photography

Description Black and white photograph by United Press International (UPI)

photographer Frank Lorenzo with typed caption. Caption: HFP030101-3/1/59-

HARTFORD, CONN.: New Haven R.R. work crews clear the tracks after a

derailment in Hartford, 3/1. Four cars of a 125 car New Haven R.R. freight train

bound for New Haven from Springfield, Mass. blocked five tracks in the Hartford

Station yard. UNITED PRESS INTERNATIONAL TELEPHOTO fl

Dimensions Primary Dimensions (overall height x width): 7 1/4 × 9in. (18.4 ×

22.9cm)