


Basic Detail Report



Title Reconstruction of the Civic Center Roof, Hartford, Connecticut

Date 1979

Primary Maker Richard Welling

Medium Drawing; black ink on paper

Description Drawing of the reconstruction of the Civic Center's roof in downtown Hartford, Connecticut, from a ground-level perspective in front of one of the entrances. The roof construction consists of a metal frame. A crane is depicted carrying some kind of building material. There are construction workers on the frame and other parts of the building.

Dimensions Primary Dimensions (image height x width): 16 x 22in. (40.6 x 55.9 cm) Sheet (height x width): 16 x 22in. (40.6 x 55.9cm)