

# Basic Detail Report

## **Title Civic Center Roof Collapse**

Date 1978

Primary Maker The Hartford Courant

Medium Photography; gelatin silver print on paper

Description View of a large, reinforced concrete sports complex; the roof has collapsed and girders and beams protrude above the entrance. Debris is in the hole created by the collapse, on the roof above the entrance, and in the street nearby. Skyscrapers, masonry, and brick multi-story buildings are in the background.

Dimensions Primary Dimensions (image height x width): 7 5/16 x 9 3/8in. (18.6 x 23.8cm) Sheet (height x width): 8 x 10in. (20.3 x 25.4cm)