

# Basic Detail Report

## **Title Workers on Side of Road**

Date 1916-1927

Primary Maker William G. Dudley

Medium Photography; gelatin emulsion on glass

Description Men stand at a road construction site. The road is being repaired, and a hole has been dug into the existing road surface. Trolley tracks are in the road and trolley wires are overhead. An automobile is on the road. Low fences, possibly serving as guard rails, run along both sides of the road.

Dimensions Plate (height x width): 8 x 10in. (20.3 x 25.4cm)