

Basic Detail Report

Title Civic Center Debris Removal, Hartford, Connecticut

Date 1978

Primary Maker Richard Welling

Medium Drawing; black ink on paper

Description Drawing of the Hartford Civic Center after the collapse of its roof, from an elevated perspective. Most of the interior of the arena is not visible through the debris, except for two small sections on the center left, where seats are visible. There are two cranes on the floor. The Masonic Hall is visible in the background.

Dimensions Primary Dimensions (Sheet a, image height x width): 16 x 22in. (40.6 x 55.9cm) Sheet (Sheet a height x width): 16 x 22in. (40.6 x 55.9cm) Primary Dimensions (Sheet b, image height x width): 16 x 11in. (40.6 x 27.9cm) Sheet (Sheet b, height x width): 16 x 11in. (40.6 x 27.9cm)