

Basic Detail Report

Title Civic Center Roof Reconstruction, Hartford, Connecticut

Date 1979

Primary Maker Richard Welling

Medium Drawing; black ink on paper

Description Drawing of the reconstruction of the Civic Center's roof after its collapse, from a slightly elevated perspective. The drawing shows one of the entrances to the arena and the construction going on above it. The top part of the arena is covered in scaffolding. There are several ladders propped up against the walls, a crane tower in the center, and another crane behind the building. Construction workers are visible on the ground.

Dimensions Primary Dimensions (Sheet a, image height x width): 18 1/8 x 23 1/2in. (46 x 59.7cm) Sheet (Sheet a height x width): 18 1/8 x 23 1/2in. (46 x 59.7cm)

Primary Dimensions (Sheet b, image height x width): 18 x 12in. (45.7 x 30.5cm)

Sheet (Sheet b height x width): 18 x 12in. (45.7 x 30.5cm)