


Basic Detail Report



Title Interior of a Deteriorated Factory Building

Date 1916-1927

Primary Maker William G. Dudley

Medium Photography; gelatin emulsion on glass

Description Interior view of a deteriorated factory building with brick walls and wooden flooring and ceiling. A major part of the flooring has given way and the basement room below is visible through the resulting open spaces.

Dimensions Plate (height x width): 8 x 10in. (20.3 x 25.4cm)