

Basic Detail Report

Title Test Car Accident on Wilbur Cross Highway, 1960

Date 1960 October 26

Primary Maker Frank Lorenzo

Medium Photography

Description Black and white photograph by United Press International (UPI)

photographer Frank Lorenzo with typed caption. Caption: HFP102601-10/26/60-

UNION, CONN.: Test driver, Patricia Jones crashes into a multi-flora rose bush

median safety barrier on the Wilbur Cross Highway, Route 15, in Union, Conn.

Miss Jones in the test conducted by the State Highway Dept. in cooperation with

an automobile manufacture (Dodge) hit the barrier on a five degree at 40 mph

and was slowed to five mph before passing through the test section. UNITED

PRESS INTERNATIONAL TELEPHOTO fl

Dimensions Primary Dimensions (overall height x width): 7 1/4 × 9in. (18.4 ×

22.9cm)